



P 0003	Etas	Høyde	Lekv	Lden	Lmoks
1	+2.0	56.5	57.2	77.8	
2	+5.0	59.3	60.0	77.5	
3	+7.6	60.9	61.5	77.0	
4	+10.5	62.0	62.6	76.3	

P 0002	Etas	Høyde	Lekv	Lden	Lmoks
1	+2.0	59.3	60.2	76.8	
2	+5.0	62.4	63.3	76.5	
3	+7.6	63.3	64.1	76.1	
4	+10.5	63.9	64.7	75.6	

P 0001	Etas	Høyde	Lekv	Lden	Lmoks
1	+2.0	59.0	59.6	69.3	
2	+5.0	62.1	62.9	71.2	
3	+7.6	63.8	63.6	71.0	
4	+10.5	63.0	63.8	70.9	

P 0004	Etas	Høyde	Lekv	Lden	Lmoks
1	+2.0	51.8	53.0	76.4	
2	+5.0	54.4	54.0	76.2	
3	+7.6	56.1	57.6	75.8	
4	+10.5	57.3	60.3	75.2	

P 0005	Etas	Høyde	Lekv	Lden	Lmoks
1	+2.0	51.1	51.9	66.1	
2	+5.0	53.5	54.2	66.3	
3	+7.6	54.4	54.9	66.3	
4	+10.5	54.8	55.4	66.3	

P 0005	Etas	Høyde	Lekv	Lden	Lmoks
1	+2.0	46.7	48.8	63.8	
2	+5.0	47.7	49.6	63.8	
3	+7.6	48.8	50.7	63.8	
4	+10.5	50.3	52.3	64.6	

P 0007	Etas	Høyde	Lekv	Lden	Lmoks
1	+2.0	42.7	45.4	64.9	
2	+5.0	48.1	50.9	68.6	

P 0010	Etas	Høyde	Lekv	Lden	Lmoks
1	+2.0	41.7	43.5	66.4	
2	+5.0	44.9	46.8	69.5	

P 0011	Etas	Høyde	Lekv	Lden	Lmoks
1	+2.0	41.2	44.1	62.3	
2	+5.0	45.0	48.0	66.9	

P 0009	Etas	Høyde	Lekv	Lden	Lmoks
1	+2.0	50.5	51.5	77.5	
2	+5.0	51.2	52.2	77.2	

P 0008	Etas	Høyde	Lekv	Lden	Lmoks
1	+2.0	49.8	51.0	76.5	
2	+5.0	51.4	53.0	76.3	

P 0016	Etas	Høyde	Lekv	Lden	Lmoks
1	+2.0	43.5	48.8	76.1	
2	+5.0	49.0	56.0	73.4	

P 0013	Etas	Høyde	Lekv	Lden	Lmoks
1	+2.0	47.8	48.4	72.8	

P 0015	Etas	Høyde	Lekv	Lden	Lmoks
1	+2.0	42.6	45.1	62.9	
2	+5.0	46.1	49.0	66.9	

P 0018	Etas	Høyde	Lekv	Lden	Lmoks
1	+2.0	43.1	45.4	64.0	
2	+5.0	46.9	49.9	64.9	

P 0019	Etas	Høyde	Lekv	Lden	Lmoks
1	+2.0	37.9	39.8	62.5	

P 0020	Etas	Høyde	Lekv	Lden	Lmoks
1	+2.0	35.6	38.6	56.5	
2	+5.0	42.3	45.2	63.0	

P 0014	Etas	Høyde	Lekv	Lden	Lmoks
1	+2.0	43.1	45.4	64.0	
2	+5.0	46.9	49.9	64.9	

P 0018	Etas	Høyde	Lekv	Lden	Lmoks
1	+2.0	43.5	46.1	64.8	
2	+5.0	46.3	49.3	64.8	

P 0017	Etas	Høyde	Lekv	Lden	Lmoks
1	+2.0	42.8	44.5	64.9	
2	+5.0	45.9	48.5	64.8	

RINGERIKE SYKEHUS.
 Støy fra trafikk. Dagens situasjon.
 Cowi AS, 09.10.2008
 Siv.ing Bjørn Leifsen